BHG3016M45 Safe Cutting Areas



Corners should be rounded.